



Background  
98th St

Background

Area 6

Area 5

Area 1

Area 7

Area 3

Area 4

Area 8

Area 2

Niagara Falls Blvd

97th St

Main St

A St

Legend

Gamma Reading ( $\mu$ R/hr)

- < 15 (1x)
- 15 - 30 (2x)
- 30 - 45 (3x)
- 45 - 60 (4x)
- 60 - 75 (5x)
- 75 - 90 (6x)
- 90 - 105 (7x)
- 105 - 120 (8x)
- 120 - 135 (9x)
- 135 - 150 (10x)
- > 150



Work Area

Notes:

Gamma survey conducted with Ludlum 3x3 Sodium Iodide Detector.  
Gamma survey measurements presenting in micro-Roentgen per hour ( $\mu$ R/hr).  
Background reading: 15  $\mu$ R/hr.



Weston Solutions, Inc.

In association with  
Scientific and Environmental Associates, Inc.,  
Avatar Environmental, LLC, Environmental Compliance Consultants  
On-Site Environmental, Inc., and Sovereign Consulting, Inc.

Figure 12: Gamma Survey Overview Map

NIAGARA FALLS BOULEVARD RADIOLOGICAL SITE  
NIAGARA FALLS, NEW YORK

U.S. ENVIRONMENTAL PROTECTION AGENCY  
REMOVAL SUPPORT TEAM 3  
CONTRACT #EP-S2-14-01

|              |                         |
|--------------|-------------------------|
| GIS ANALYST: | T. BENTON               |
| EPA OSC:     | E. DALY                 |
| RST SPM:     | B. NWOSU                |
| FILENAME:    | 161020 NFB Gamma OV.mxd |

DATE MODIFIED: 4/27/2017